Cost of interim control (tape) - $0.10

Cost of phone call to report this hazard - $0.00

Cost of the injury avoided – $0.00

Protection to our most precious resource, our people – Priceless!

A LCDR at CFA Okinawa took the time to report this unsafe working condition to Safety. The handrails, outside of the main entrance to PSD had rusted through. As you can see, it would have been very easy for someone to cut their hand on the rusted out edges of the handrail. This was a simple interim fix that will do until the handrails are replaced.

If you see safety hazards such as this, please report them to your safety rep or to your safety office via email or telephone.

PS The Safety Manager mentioned that he had walked by this many times and never noticed – so if YOU notice something unsafe – PLEASE report it, you may be the only person